

SILBRAZE F

Brazing Fluxes

AWS A/SFA 5.31 **FB3-F**

DIN 8511	
F-SH 1	

KEY FEATURES:

- Silver brazing flux
- Contains complex fluorides and boron components
- Excellent cleaning action and capillary flow
- Can be mixed with water and used in the paste form

TYPICAL APPLICATIONS:

• Brazing of steel, copper and silver

DIRECTION:

Before Use: Remove oil, grease or other contaminants from the surface to be brazed. Check pH in case of over shelf life. Shake well to homogenize.

After Use: Clean flux residue from brazed joint using hot water 60°C for best results. If hot water unavailable, room temperature water may also be used. Remaining flux to be kept in closed container. Although fluxes are milder to human hygienic care is recommended.

CLEANING:

Remove Flux residues by rising in hot water.

PHYSICAL PROPERTIES :		
Form	Filler Metal Type	Activity Temperature Range, °C
Powder	Bag and BCu	650-870

PARAMETERS - PACKING DATA:		
Packing Form Bottle	Wt/Bottle 500 gms	

ADOR WELDING LIMITED www.adorwelding.com